



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	59261
-------------------	-------

Customer Information:

Company	WEBB RESEARCH CORPORATION	Date	4/7/2010
Contact	Bill Robson		
PO Number	TBD		

Serial Number	WEBB Glider-0092
Model Number	WEBB Glider

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

1. The CT mount weld assembly was found to have been cracked.

Services Performed:

<ol style="list-style-type: none">1. Performed initial diagnostic evaluation.2. Installed NEW Glider CT mount weld assembly, flatless penetrator.3. Performed "Final" calibration of the temperature & conductivity sensors.4. Calibrated the pressure sensor.5. Performed complete system check and full diagnostic evaluation.
--

Special Notes:

--