



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

72412

Customer Information:

Company WEBB RESEARCH CORPORATION **Date** 2/13/2013

Contact Peter Collins

PO Number TWR7722

Serial Number WEBB Glider-0189

Model Number WEBB Glider

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. The anti-foulant devices appeared "dirty".

Services Performed:

1. Performed initial diagnostic evaluation.
2. Calibrated the pressure sensor.
3. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
4. Installed NEW AF24173 Anti-foulant cylinder(s).
5. Performed complete system check and full diagnostic evaluation.

Special Notes:

--