**Customer:** 

WEBB RESEARCH CORPORATION

## Temperature Calibration Report

Job Number:	82667	Date of Re	port:	2/9/2015
Model Number	WEBB Glider	Serial Num	ber:	WEBB Glider-0039
Temperature sensors are normally calibrated 'as received', without adjustments, allowing a determination sensor drift. If the calibration identifies a problem, then a second calibration is performed after work is completed. The 'as received' calibration is not performed if the sensor is damaged or non-functional, or by customer request.  An 'as received' calibration certificate is provided, listing coefficients to convert sensor frequency to temperature. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients. The coefficient 'offset' allows a small correction for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair apply only to subsequent data.				
'AS RECEIVED CALIBRATION'  Performed  Not Performed				
Date: 2/7/2015		Drift since last cal:	0.00	00 Degrees Celsius/year
Comments:				
				_
CALIBRATION A	AFTER REPAIR'	□ P	erformed	✓ Not Performed
Date:		Drift since Last cal:		Degrees Celsius/year
Comments:				